

22/01/2024

Letter No. 14250:

Subject: Structural safety report.

Director of the Field Safety Center-Batha, Riyadh

In reference to the above topic and the field visit to the Yara International (Boys) School's building and based on the virtual examination, we inform you of the following:

- The building is structurally sound and does not contain any cracks or fissures.
- Architectural safety means, such as stairs and escape corridors, are available inside the building.

The building is according to the Saudi building code.

- The building was protected by appropriate safety means and systems.

Sd/

Azm Engineering Consulting Office

Riyadh

Saudi Arabia

Azma



التاريخ : ٢٠٢٤/٠١/٢٢

خطاب رقم : ١٤٢٥٠

الموضوع : تقرير سلامة انشائية.

السيد/ مدير مركز السلامة الميداني - بالبطحاء **حفظه الله**

السلام عليكم ورحمه الله وبركاته ,, ,

تحية طيبة ,, وبعد,

عظفا على الموضوع أعلاه وعلى الزيارة الميدانية ل مبنى مدارس يارا العالمية (بنين) وعلى الكشف الظاهري نفيديكم بالتالي :
- المبنى سليم انشائيا ولا يوجد به أي تصدعات او تشققات.
- وسائل السلامة المعمارية من سلالم وممرات هروب متوفرة داخل المبنى حسب الكود السعودي للبناء.
- تم حماية المبنى بوسائل وأنظمة السلامة المناسبة.

مكتب عزم للاستشارات الهندسية





Date: 22/01/2024

Letter No. 14251:

Subject: Structural Safety Report.

Director of the Field Safety Center-Batha, Riyadh

In reference to the above topic and the field visit to the Yara International (Girls) School's building and based on the virtual examination, we inform you of the following:

- The building is structurally sound and does not contain any cracks or fissures.
- Architectural safety means, such as stairs and escape corridors, are available inside the building

The building is according to the Saudi building code.

- The building was protected by appropriate safety means and systems.

Sd/

Azm Engineering Consulting Office

Riyadh

Saudi Arabia

Azma



التاريخ : ٢٠٢٤/٠١/٢٢

خطاب رقم : ١٤٢٥١

الموضوع : تقرير سلامة انشائية.

السيد/ مدير مركز السلامة الميداني - بالبطحاء **حفظه الله**

السلام عليكم ورحمه الله وبركاته ,, ,

تحية طيبة ,, وبعد,

عظفا على الموضوع أعلاه وعلى الزيارة الميدانية ل مبنى مدارس يارا العالمية (بنات) وعلى الكشف الظاهري نفيديكم بالتالي :
- المبنى سليم انشائيا ولا يوجد به أي تصدعات او تشققات.
- وسائل السلامة المعمارية من سلالم وممرات هروب متوفرة داخل المبنى حسب الكود السعودي للبناء.
- تم حماية المبنى بوسائل وأنظمة السلامة المناسبة.

مكتب عزم للاستشارات الهندسية

